## **Trouble Shooting Guide**

Problem	Cause	Solution
Premature Wear	<ul> <li>Cutting speed is too fast</li> <li>Hard/Abrasive work-piece material</li> <li>Speed and/or feed is too light</li> <li>Helix angle is incorrect for application</li> <li>Re-cutting chips</li> </ul>	<ul> <li>Decrease spindle speed</li> <li>Use coatings (TiCN, TiAIN, AITiN)</li> <li>Increase speed and/or feed</li> <li>Select tool with appropriate helix angle</li> <li>Adjust speed &amp; feed, axial and/or radial D.O.C., Increase coolant pressure and/or air to clear chips.</li> </ul>
Edge Chipping	<ul> <li>Feed rate too aggressive</li> <li>Feed rate too aggressive on initial cut</li> <li>D.O.C. too aggressive</li> <li>Tool rigidity</li> <li>Work-piece rigidity</li> <li>Machine tool rigidity</li> </ul>	<ul> <li>Reduce feed rate</li> <li>Reduce feed rate on initial pass</li> <li>Decrease axial and/or radial D.O.C.</li> <li>Change tool holder, hold shank deeper and/or use shorter tool</li> <li>Re-fixture work-piece and/or improve setup</li> <li>Check spindle for run-out</li> </ul>
Breakage	<ul> <li>Feed rate too aggressive</li> <li>D.O.C. too aggressive</li> <li>Excessive tool overhang</li> <li>Chip packing</li> <li>Excessive wear</li> </ul>	<ul> <li>Reduce feed rate</li> <li>Reduce axial and/or radial D.O.C.</li> <li>Hold shank deeper, use shorter end mill</li> <li>Adjust speed and/or feed, select end mill with fewer flutes, increase coolant pressure and/or air</li> <li>Re-grind tool sooner</li> </ul>
Chip Packing	<ul> <li>Speed and/or feed too aggressive</li> <li>Flute gullet too small for chips</li> <li>Insufficient coolant volume and/or pressure</li> </ul>	<ul> <li>Reduce speed and/or feed</li> <li>Use end mill with less flutes</li> <li>Increase coolant and/or air pressure, reposition nozzle to point of cut</li> </ul>
Chattering	<ul> <li>Speed and/or feed too aggressive</li> <li>Tool rigidity</li> <li>Work-piece rigidity</li> <li>Machine tool rigidity</li> <li>D.O.C. too aggressive</li> <li>Wrong tool geometry</li> </ul>	<ul> <li>Reduce speed and/or feed</li> <li>Change tool holder, hold shank deeper and/or use shorter tool</li> <li>Re-fixture work-piece and/or improve setup</li> <li>Check spindle for run-out</li> <li>Reduce axial and/or radial D.O.C.</li> <li>Use Whisperkut™ Type end mill</li> </ul>
Burrs	<ul> <li>Incorrect speed &amp; feed</li> <li>Helix angle is incorrect for application</li> <li>Primary cutting edge(s) are dull</li> </ul>	<ul> <li>Adjust speed &amp; feed</li> <li>Change to correct helix angle, use climb milling</li> <li>Re-grind tool sooner</li> </ul>
Poor Finish	<ul> <li>Feed rate too aggressive</li> <li>Speed is too slow</li> <li>D.O.C. too aggressive</li> <li>Excessive wear</li> </ul>	<ul> <li>Reduce feed rate</li> <li>Increase spindle speed (RPM)</li> <li>Reduce axial and/or radial D.O.C.</li> <li>Re-grind tool sooner</li> </ul>
Poor Dimensional Accuracy	<ul> <li>D.O.C. too aggressive</li> <li>Tool Rigidity</li> <li>Machine tool rigidity</li> </ul>	<ul> <li>Reduce axial and/or radial D.O.C.</li> <li>Use tool with more flutes</li> <li>Check, inspect &amp; repair machine tool, tool holder and fixtures</li> </ul>

Should your milling problems persist please feel free to contact our Technical Service Department for further assistance at 1-800-444-6455.